Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0010, W0017, W0015, W0003, W0005, W0001, W0008, W	NA	SRIRAMA TEMPLE
Segment No.	**Total Length (m)**	
13/C-W0010/S011755	203.41	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	73.56	77.510441	13.057733	77.511104	13.057872	I0231	W0005
2	28.95	77.510232	13.058297	77.510497	13.058268	W0015	W0017
3	100.90	77.508492	13.058859	77.509396	13.058644	W0017	I10009

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
IMPROVEMENTS TO FOOTPATH IN 2ND CROSS ROAD & OTHER ROADS NEAR SRIRAMA TEMPLE	1500000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Footpath Layering	
Tender	**Work Details**	**Job No. / Work Code**
Tender		013-15-00004
Work Order No.	**Work Order Date**	**Period of Extention**
EE\DD\WO\338\14-15	31/03/2015	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B UMESH		0.00
Phone No.	**E-Mail ID**	
9980485938		

Zone: DASARAHALLI Ward No: 13 Ward Name: Mallasandra Street ID: W0010, W0017, W0015, W0003,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು.

Field Inspection Details

Number of Trees	Any Other Information	Name
0		nagabhushan G
Date of Inspection	**Remarks**	
15/09/2015		

Category	Image	Photo Remark
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDDEGOWDA	15/09/2015	15/10/2015	
EE	MALATHESHA R	15/09/2015	15/10/2015	
AEE	JAYALINGAPPA BL	15/09/2015	15/10/2015	
AE	NAGABHUSHAN G	15/09/2015	15/10/2015	
AE	NAGABHUSHAN	15/09/2015	15/10/2015	

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0010, W0017, W0015, W0003,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0010, W0017, W0015, W0003, W0005, W0001, W0008, W	NA	SRIRAMA TEMPLE
Segment No.	**Total Length (m)**	
13/C-W0010/S011755	203.41	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	73.56	77.510441	13.057733	77.511104	13.057872	I0231	W0005
2	28.95	77.510232	13.058297	77.510497	13.058268	W0015	W0017
3	100.90	77.508492	13.058859	77.509396	13.058644	W0017	I10009

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
IMPROVEMENTS TO FOOTPATH IN 2ND CROSS ROAD & OTHER ROADS NEAR SRIRAMA TEMPLE	1500000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Footpath Layering	
Tender	**Work Details**	**Job No. / Work Code**
Tender		013-15-00004
Work Order No.	**Work Order Date**	**Period of Extention**
EE\DD\WO\338\14-15	31/03/2015	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
		Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B UMESH		0.00
Phone No.	**E-Mail ID**	
9980485938		

Zone: DASARAHALLI Ward No: 13 Ward Name: Mallasandra Street ID: W0010, W0017, W0015, W0003,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು.